Seal kit replacement.
Steering Cylinder 71500 and 71501

Seal kit part number: 75500

Seal kit replacement have to be done by a qualified mechanic.


Required tools:
- C-Spanner for Ø112 mm ring, Pos. 18
- Circlip Plier for removal/install of Pos, 20
- Assorted range of general hand tools.

General precautions:
Prolonged skin contact with hydraulic oil is to be avoided. Always use necessary personal protection
The replacement have to be done in a clean environment. Use only clean tools and rags.

Seal kit content:



See assembly drawing for construction details and seal locations.
Take special care not to damage new seals and sealing surfaces.
Apply a thin layer of clean hydraulic oil on the new seals prior to install/cylinder assembly.



Hydraulic Cylinder, 71500, 71501

Assembly drawing